

SCAN KING

Assembly Instruction

Attach the mounting pole to your mast using clamp and 'U' Bolt supplied and tighten the screw

Screw the four radials into the base and tighten.

Fit PL 259 plug to coax and pass through the mounting pole and fasten to the base of the antenna, Low Loss 50 Ohm coax is recommended.

Place the antenna into mounting pole and secure with screw supplied.

Mount your Scan King as high as possible keeping clear of buildings and any overhead cables.

